LMA District Cover Sheet

Spring 2012 Levee Inspection Results

Reclamation District No. 1601 Twitchell

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				
	** Non-receipt of Su	ımmer or Winter Inspe	ection Reports may effec	ct overall annual rating
SPRING INSPECTIONS: Overall maintenance deficiencies are rated for the overall maintenance within the attached unit of the overall maintenance of the overal	d using the same crite nce rating shown abo	ria in the spring and in	the fall.	
omments				

Unit Cover Sheet

Spring 2012 Levee Inspection Results

Reclamation District No. 1601 Twitchell

Waterway	Bank	Unit Miles
Unit No. 01 Threemile Slough	Left	2.47

	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/3/2012 - 4/3/2012			
DWR Inspector	Richard Willoughby			
Accompanied By				

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

http://cdec.water.ca.gov/lma.html

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

Levee Inspection Report By Mile - Spring 2012

Reclamation District No. 1601 Twitchell

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Threemile Slough	Left	2.47	04/03/2012 04/03/2012	Richard Willoughby

LMR	Levee	Mile	Catagani	Item	Location	Rating	Action/Comment	GPS Latitude	e/Longitude	Issue No.
No.	Start	End	Category	пеш	tion	ing +	Action/Comment	Start	End	Photo
1	0.00	0.00	Earthen Levee	Operations & Maintenance Manuals	CR	A Ma		0	0	3
								DWR ID: DWR_RD		_3
2	0.00	0.00	Earthen Levee	Emergency Supplies & Equipment	CR	A Ma		0	0	4
				4-1				DWR ID: DWR_RD	1601_01_s _ 2012	_4
3	0.00	0.00	Earthen Levee	Flood Preparedness & Training	CR	A Ma		0	0	6
				···				DWR ID: DWR_RD	1601_01_s _ 2012_	_6
4	0.03	2.45	Earthen Levee	Vegetation	WS	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.121827 ° -121.682620 ° - DWR ID: DWR_RD		2 Y _2
5	0.03	2.45	Earthen Levee	Vegetation	LS	M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	38.121818 ° -121.682620 ° - DWR ID: DWR_RD		1
6	0.10	1.31	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M Ma	C2 : Regrade the crown roadway for proper drainage.	38.120883 ° -121.682775 ° -		5 Y _5

* Rating

A : Acceptable

M : Minimally Acceptable

U : Unacceptable

N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain + Issue Type Ma : Mainter

Ma : Maintenance Deficiancy Ob : Design & System Obsolescence En : Enforcement

Levee Inspection Report By Mile - Spring 2012

Reclamation District No. 1601 Twitchell

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Threemile Slough	Left	2.47	04/03/2012 04/03/2012	Richard Willoughby

Levee Mile Report Line	4		
· ·	·		
Start Levee Mile	0.03		
End Levee Mile	2.45		
Location	Water Side		
Category	Earthen Levee		
Item	Vegetation		
Looking northwest at typical of landside and waterside of levee.			

richard_s_20120404_221.jpg

Levee Mile Report Line	6			
Start Levee Mile	0.10			
End Levee Mile	1.31			
Location	Crown			
Category	Earthen Levee			
Item	Crown Surface / Depressions / Rutting			
Looking north at holes on levee crown.				

richard_s_20120313_110.jpg

Levee Mile Report Line	6
Start Levee Mile	0.10
End Levee Mile	1.31
Location	Crown
Category	Earthen Levee
Item	Crown Surface / Depressions / Rutting
Looking south at crown s	surface rutting.

richard_s_20120313_111.jpg







* Location	
LS : Land Side	
WS : Water Side	

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monit : Corrected : Acceptable but Monitor & Maintain

+ Issue Type

Ma: Maintenance Deficiancy
Ob: Design & System Obsolescence
En: Enforcement